



Manuale Crogiolo A37936

Quick Start Guide

To protect the environment, we have prepared for you this quick start guide. Before operating the unit, please read it carefully.

Application

Device for tinning lead ends.

Unit setup and operation



P- Adjustment knob W – Power on switch T – Pot O – Ventilatioon holes

- - Place the device on a stable surface.
 - Plug the power cord into the appropriate outlet.
 - Place the solder alloy previously cut into small pieces inside the pot respecting the maximum level.
 - Turn on the power using the power on switch on the device.
 - Set the desired level of temperature and wait until the alloy is melted.
 - If oxides float on the surface, they must be removed to preserve the solder clean.

www.cepeitalia.it

Cepeitalia SrI Via M. Buonarroti, 15 Cesano Boscone MI - Tel. 02.4073747 info@cepeitalia.it





Precautions

- Do not turn on the unit immediately after moving it from a cold to a warm room. Condensation may damage the device.
- Damaged power cord must be immediately replaced by a qualified technician.
- The device can be used only in well-ventilated areas.
- Do not cover the ventilation holes.
- Never operate the unit with wet hands or when wires are wet as this could cause a short circuit or electric shock.
- Do not place hot device near the flammable objects, liquids, or gases.
- Do not use the station to heat the plastic as it can produce toxic fumes.
- There is a danger of burs by liquid solder.
- Use the proper protective clothing.
- Do not leave the unit unattended.
- The unit should be kept out of reach of children.
- Do not use the soldering pot for purposes other than melting the solder.
- After finishing the work, turn off the power, unplug the power cord and wait for the device to cool down.
- It is forbidden to make any construction modifications to the device. Unauthorized construction modifications will result in loss of warranty and may also cause a malfunction or an accident.
- Never touch the heating element.
- Worn electrical equipment may not be disposed of with other household waste. Worn electrical equipment must be stored in places designated for that.

Cepeitalia Srl Via M. Buonarroti, 15 Cesano Boscone MI - Tel. 02.4073747 info@cepeitalia.it